

012137



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D4775-041
Job Sheet 200923



Part No: D4775-041

Job Qty: 4 pcs

Part Name: Strut Assembly



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/19/19

Job Tracking No:

Due Date: 10/2/19

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG REV C SHEET 1 IPP REV:A 13.02.28 NEW ISSUE DD VERF:JFS IPP REV:B 13.08.26 PB1 DD
VERF:JLM IPP REV:C 13.09.26 AS PER REV.B DD VERF:JLM IPP REV:D 14.01.10 AS PER REV.C DD
VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
110	Packaging 1 - Pick Kit	4 pcs	10/2/19		0.00	0.00	Packaging 1 - 1		
							Packaging 1 - 2		
							Packaging 1 - 3		
							Packaging 1 - 4		
							Packaging 1 - 5		
							Packaging 1 - 6		
							Packaging 1 - 7		
							Packaging 1 - 8		
							Packaging 1 - 9		
							Packaging 1 - 10		
							Packaging 1 - 11		
							Packaging 1 - 12		
							Packaging 1 - 13		
							Packaging 1 - 14		
							Packaging 1 - 15		
							Packaging 1 - 16		
							Packaging 1 - 17		
							Packaging 1 - 18		
							Packaging 1 - 19		
							Packaging 1 - 20		
							Packaging 1 - 21		
							Packaging 1 - 22		
							Packaging 1 - 23		
							Packaging 1 - 24		
							Packaging 1 - 25		
							Packaging 1 - 26		
							Packaging 1 - 27		
							Packaging 1 - 28		
							Packaging 1 - 29		
							Packaging 1 - 30		

SEP 27 2019

Plex 9/19/19 10:30 AM Dart.lajeunesse.marie

					Packaging 1 - 31	
					Packaging 1 - 32	
					Packaging 1 - 33	
					Packaging 1 - 34	
					Packaging 1 - 35	
					Packaging 1 - 36	
120 Small Fab - 2 - B4B	4 pcs	10/2/19	0.00 1.66		Small Fab - 1 - B4B	
					Small Fab - 2 - B4B	
					Small Fab - 3 - B4B	
					Small Fab - 4 - B4B	
					Small Fab - 5 - B4B	
					Small Fab - 6 - B4B	
					Small Fab - 7 - B4B	
					Small Fab - 8 - B4B	
					QC 5 - 10	
					QC 5 - 12	
					QC 5 - 17	
					QC 5 - 18	
					QC 5 - 19	
					QC 5 - 22	
130 QC 5	4 pcs	10/2/19	0.00 0.00		QC 5 - 24	
					QC 5 - 3	
					QC 5 - 43	
					QC 5 - 49	
					QC 5 - 51	
					QC 5 - 58	
					QC 5 - 68	
					QC 5 - 9	
					QC 5 - 50	
					QC 5 - 30	
					QC 5 - 40	
					QC 5 - 61	
					QC 5 - 81	
140 Packaging 3-1 - Stock - B4B	4 pcs	10/2/19	0.00 0.00		Packaging 3 - 1 - B4B	
					Packaging 3 - 2 - B4B	
					Packaging 3 - 3 - B4B	
					Packaging 3 - 4 - B4B	
					Packaging 3 - 5 - B4B	
					Packaging 3 - 6 - B4B	
					Packaging 3 - 7 - B4B	
					Packaging 3 - 8 - B4B	
					Packaging 3 - 9 - B4B	
					Packaging 3 - 10 - B4B	
					Packaging 3 - 11 - B4B	
					Packaging 3 - 12 - B4B	
					Packaging 3 - 13 - B4B	
					Packaging 3 - 14 - B4B	
					Packaging 3 - 15 - B4B	
					Packaging 3 - 16 - B4B	
					Packaging 3 - 17 - B4B	
					Packaging 3 - 18 - B4B	
					Packaging 3 - 19 - B4B	
					Packaging 3 - 20 - B4B	
					Packaging 3 - 21 - B4B	
					Packaging 3 - 22 - B4B	
					Packaging 3 - 23 - B4B	
					Packaging 3 - 24 - B4B	
					Packaging 3 - 25 - B4B	
					Packaging 3 - 26 - B4B	

SEP 30 2019

SEP 30 2019 40 9-89

					Packaging 3 - 27 - B4B	
					Packaging 3 - 28 - B4B	
					Packaging 3 - 29 - B4B	
					Packaging 3 - 30 - B4B	
					Packaging 3 - 31 - B4B	
					Packaging 3 - 32 - B4B	
					Packaging 3 - 33 - B4B	
					Packaging 3 - 34 - B4B	
					Packaging 3 - 35 - B4B	
					Packaging 3 - 36 - B4B	
150	QC 21 - SA	4 pcs	10/2/19	0.00 0.00	QC 21 - SA - 21	DAG
					QC 21 - SA - 70	21
					QC 21 - SA - 53	9-69

Part Op 110 - (Pick Kit)

Descriptions: 120 - (Small Fab) 1- APPLY PROSEAL ON D4776-1 STRUT AND ASSEMBLE AS PER DWG A/R PROSEAL

BATCH: 5176610 2- ENSURE HELICOIL DOES NOT BLOCK HOLE (SEE NOTE 9)

130 - (QC5- Inspect part completeness to step on W/O)

140 - (Identify as per dwg & Stock Location: _____)

150 - (QC21- Final Inspection - Work Order Release)

OCT 01 2019

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
AN3-10A	BOLT	8 Ea (2 ea)	110-Packaging 1 - Pick Kit	3205991
D4775-1	Strut Tube	4 pcs (1 ea)	110-Packaging 1 - Pick Kit	3205761
D4776-1	Basket Strut Clevis	4 pcs (1 ea)	110-Packaging 1 - Pick Kit	1x607347 - 3x5187143
D4776-5	Spacer	16 pcs (4 ea)	110-Packaging 1 - Pick Kit	3206111
D4777-1	Rod End Bearing	4 pcs (1 ea)	110-Packaging 1 - Pick Kit	3215786
MS21042L3	Nut	8 Ea (2 ea)	110-Packaging 1 - Pick Kit	3211533
MS21209-F615	Heli-Coil	4 Ea (1 ea)	110-Packaging 1 - Pick Kit	3199552

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
110-Packaging 1 - Pick Kit	AN3-10A	8	218	0
	D4775-1	4	41	0
	D4776-1	4	31	0
	D4776-5	16	124	0
	D4777-1	4	31	0
	MS21042L3	8	1,759	0
	MS21209-F615	4	43	0

Part Specifications

Specifications could not be found.

Plex 9/19/19 10:30 AM Dart.lajeunesse.marie



Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

Route update only ☐

NCR No. _____

DISPOSITION		DEPARTMENT/PROCESS																																																																																			
Job: _____	Rework ☐ Scrap ☐ Use-as-is ☐	Skid-tube ☐ Machining ☐ Large Fab ☐	Cross tube ☐ Small Fab ☐ Finishing ☐	Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐	Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐																																																																																
Date: _____	Sequence #: _____	QTY Affected: _____		MRB (QSI042) _____																																																																																	
Description Work Order Deviation		Disposition																																																																																			
Root Cause <table border="1"><tr><td>Operator</td><td>☐</td></tr><tr><td>Manufacturing Process</td><td>☐</td></tr><tr><td>Equip/Tooling</td><td>☐</td></tr><tr><td>Handling/Preservation</td><td>☐</td></tr><tr><td>Material</td><td>☐</td></tr><tr><td>Product Improvement</td><td>☐</td></tr><tr><td>Process Improvement</td><td>☐</td></tr><tr><td>Human Factors</td><td>☐</td></tr></table>		Operator	☐	Manufacturing Process	☐	Equip/Tooling	☐	Handling/Preservation	☐	Material	☐	Product Improvement	☐	Process Improvement	☐	Human Factors	☐	FAULT CATEGORY <table border="1"><tr><td>Pressure/Forced</td><td>☐</td><td>Contamination</td><td>☐</td><td>Power Loss/Surge</td><td>☐</td><td>Positioned Wrong</td><td>☐</td></tr><tr><td>Bending</td><td>☐</td><td>Misaligned/off center</td><td>☐</td><td>Folio/Program</td><td>☐</td><td>Outside Tolerance</td><td>☐</td></tr><tr><td>Crushing</td><td>☐</td><td>BOM/Route</td><td>☐</td><td>Grain Direction</td><td>☐</td><td>Drawing</td><td>☐</td></tr><tr><td>Cracks</td><td>☐</td><td>Broken/Damage/Defect</td><td>☐</td><td>Weld</td><td>☐</td><td>Finish</td><td>☐</td></tr><tr><td>Crimp/Kink/Ripple/Wave/Twist</td><td>☐</td><td>Incomplete/Unclear Instructions</td><td>☐</td><td>Wrong Stock Pulled</td><td>☐</td><td>Part Lost/Missing</td><td>☐</td></tr><tr><td>Marks/Chatter</td><td>☐</td><td>Drill Holes</td><td>☐</td><td>Out of Sequence</td><td>☐</td><td>Misread</td><td>☐</td></tr><tr><td>Mislabeled</td><td>☐</td><td>Fit/Function</td><td>☐</td><td>Off-set/Set-up</td><td>☐</td><td></td><td></td></tr><tr><td colspan="2">Other/Details:</td><td colspan="6"></td></tr></table>				Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐	Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐	Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐	Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐	Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐	Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐			Other/Details:							
		Operator	☐																																																																																		
		Manufacturing Process	☐																																																																																		
Equip/Tooling	☐																																																																																				
Handling/Preservation	☐																																																																																				
Material	☐																																																																																				
Product Improvement	☐																																																																																				
Process Improvement	☐																																																																																				
Human Factors	☐																																																																																				
Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐																																																																														
Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐																																																																														
Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐																																																																														
Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐																																																																														
Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐																																																																														
Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐																																																																														
Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐																																																																																
Other/Details:																																																																																					
Completed By		Lead hand / Supervisor																																																																																			
		QC / QA Coordinator																																																																																			